



Tel: +44 (0)1394 380307
Fax: +44 (0)1394 385156
E-mail: info@lindos.co.uk

Lindos Electronics, Saddlemakers Lane
Melton, Woodbridge, Suffolk, IP12 1PP, UK

MiniSonic MS20 – v1.2

Bug fixes:

1. Fixed bug in firmware v1.1 the caused the wrap limits for the calibration values to be set to the wrap limits of the cursor that was last used.
2. Added segment 'h' to 'Sound Card Test' sequence definition.

CMS 6.6.2007